

TII, RSI Review, Unresolved Design Issues

ROUTE: N71

Ubipix Tag ID: 1082

Hazard ID:

N71KY_180.0_179.000000000_6194061f

Mainline or Side Road: M

Lat/Long:

52.004952000000003, -

9.5123080000000009

Link to Ubipix:



RSI Date: 08.09.14

Review Date: 13.01.17

Problem Category: Roadside_hazard

Problem Description:

Risk of collision with inconspicuous boundary wall.

Severity: M

Likelihood: U

Risk Rating: L

Broad Solution: Signage

Feasibility Stage Solution:

Reflective paint / signage should be applied / erected to the parapet wall, so that it is visible to oncoming traffic.

Residual Risk: L

Priority Ranking: 5

Cost Estimate: €3125



TII, RSI Review, Unresolved Design Issues

ROUTE: N71

Ubipix Tag ID: 600

Hazard ID:

N71KY_180.0_179.000000000_58eb05d1

Mainline or Side Road: M

Lat/Long:

52.005564999999997, -
9.5085110000000004

Link to Ubipix:



RSI Date: 08.09.14

Review Date: 13.01.17

Problem Category: Roadside_hazard

Problem Description:

Risk of collision with inconspicuous roadside wall. Particular risk at night.

Severity: S

Likelihood: U

Risk Rating: M

Broad Solution: Signage

Feasibility Stage Solution:

Reflective chevrons should be applied to the wall.

Residual Risk: M

Priority Ranking: 5

Cost Estimate: €1875

